

Docket No. 59764.21541
Customer No. 30734



10/072,755

PATENT

co/c

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 6,963,146 B2)
Inventors: James W. ZECCA, et al.)
Issue Date: November 8, 2005)
For: MODULAR POWER CONTROL APPARATUS)

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
ATTENTION: CERTIFICATE OF CORRECTION BRANCH

Sir:

Pursuant to 35 U.S.C. § 254 and 37 C.F.R. § 1.322, this is a request for the issuance of a Certificate of Correction in the above-identified patent. Two (2) copies of PTO Form 1050 are appended. The Certificate of Correction involves replacing the drawings as printed in the above-identified patent with the attached four (4) sheets of replacement drawings (FIGS. 1-4). These formal drawings were deposited with the U.S. Postal Service via first class mail on March 15, 2002 and accepted by the Examiner in the Notice of Allowance dated June 15, 2005.

The mistake identified in the appended Form occurred through no fault of the Inventors and no fee is due. Issuance of the Certificate of Correction containing the correction is respectfully requested.

Respectfully submitted,

BAKER & HOSTETLER LLP

P. Alan Larson
Reg. No. 53,184

Date: January 3, 2006
Washington Square, Suite 1100
1050 Connecticut Avenue, N.W.
Washington, D.C. 20036
Phone: (202) 861-1500
Fax: (202) 861-1783

Certificate
JAN 05 2006
of Correction

JAN 06 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,963,146 B2
DATED : November 8, 2005
INVENTOR(S) : James W. ZECCA, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

DRAWINGS

Please replace the drawings as printed in the Letters Patent with the attached four (4) sheets of formal drawings (FIGS. 1-4).

MAILING ADDRESS OF SENDER:

Baker & Hostetler LLP
Washington Square, Suite 1100
1050 Connecticut Avenue, N.W.
Washington, D.C. 20036

PATENT NO. 6,963,146 B2

No. of additional copies

⇒ 1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

JAN 06 2006

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,963,146 B2
DATED : November 8, 2005
INVENTOR(S) : James W. ZECCA, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

DRAWINGS

Please replace the drawings as printed in the Letters Patent with the attached four (4) sheets of formal drawings (FIGS. 1-4).

MAILING ADDRESS OF SENDER:

Baker & Hostetler LLP
Washington Square, Suite 1100
1050 Connecticut Avenue, N.W.
Washington, D.C. 20036

PATENT NO. 6,963,146 B2

No. of additional copies

⇒ 1

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comment on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

JAN 06 2006



Inventors: James W: ZECCA, et al.
U.S. Patent No.: 6,963,146 B2
Date of Patent: November 8, 2005
Replacement Sheet 1 of 4




FIG - 1

JAN 06 2006







FIG - 2



JAN 06 2006



JAN 06 2006




FIG - 4